



## 1. Supplementary shunt's parts of electronic type

1. Lever
2. Lever guide
3. Screw(M4XL22, M4X35)
4. M4 NUT




## 2. Shunt's of electronic type




### 3. Shunt mounting method

a. Insert the nut into the hole




M4 NUT

b. Set the lever




Lever

c. Insert lever guide into the lever's hole



Lever Guide

d. Fasten two screws



Screw(M4X35)

Screw(M4X22)

e. product after working

