

CERTIFICATE OF COMPLIANCE

Certificate Number E506311
Report Reference E506311-20191224
Issue Date 2020-APRIL-16

Issued to: LS ELECTRIC Co Ltd
95 Baekbong-ro Heungdeok-gu
Cheongju-si Chungcheongbuk-do 28439 KOREA

**This certificate confirms that
representative samples of**

COMPONENT - PANELBOARD AND SWITCHBOARD
ACCESSORIES
SEE ADDENDUM PAGE

Have been investigated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety:
Additional Information:

UL 67 Panelboards
See the UL Online Certifications Directory at
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Recognized Component Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number E506311
Report Reference E506311-20191224
Issue Date 2020-APRIL-16

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Component – Panelboard Components,

- Branch Strap, Cat Nos.

70211172813, 70211172814, 70211172815, 70211172816, 70211172817, 70211172818,
70211172819, 70211172820, 70211172821, 70211172822, 70211173813, 70211173814,
70211173815, 70211173816, 70211173825, 70211173826, 70211173817, 70211173818,
70211173819, 70211173820,
70211173821, 70211173822, 70211173823, 70211173824, 70211176801, 70211176802,
70211176803, 70211176804, 70211176805, 70211176806, 70211176807, 70211176808,
70211176809

- Vertical Busbar, Cat Nos. 70211172823, 70211172824, 70211172825

- Mounting Bracket, Cat Nos.

50511172804, 50511172805, 50511173804, 50511173805, 50511176802

- Insulation Barrier, Cat Nos. 67211172901

- P-Cover, Cat Nos.

58611172806, 58611173803, 58611173805, 58611176801, 58611173806, 58611176802

- P-Cover Filler, Cat Nos. 58611172807, 58611173804

- P-Cover Blank, Cat Nos.

58611172813, 58611172814, 58611172815, 58611172816, 58611172817,
58611172818, 58611172819, 58611172820

- Support Brackets, Cat Nos.

54611172901, 58411172901, 58411172902, 58411172903

- Bus support, Cat Nos. 62411172802



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

